hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner of Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on April 19, 2005 IFW COFC **PATENT** 

In re Patent of:

Mart Ortiz et al.

Patent No.:

6,808,483

**6**. 36,330

Issue Date:

October 26, 2004

Title:

IMPLANTABLE HEART ASSIST DEVICES AND METHODS

Confirmation No.:

7667

Atty Docket No.:

SPEN-08

Cincinnati, Ohio

April 19, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

## REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKES

It is respectfully requested that a Certificate of Correction be issued for the patent identified in the heading. The patent contains errors that occurred through the fault of the Patent Office as follows:

This request is made under 37 C.F.R. § 1.322 to correct these mistakes.

Column 5, line 45, change "34" to --3A-- as appears in the originally filed specification at page 11, line 18.

Column 6, line 34, after "device" insert --10- as appears in the originally filed specification at page 13, line 16.

Column 6, line 39, after "device" insert --10- as appears in the originally filed specification at page 13, line 20.

Column 6, line 42, after "ventricle" insert --20- as appears in the originally filed specification at page 13, line 23.

Column 6, line 46, after "aorta" insert --30- as appears in the originally filed specification at page 14, line 3.

Column 6, line 53, after "device" insert --10- as appears in the originally filed specification at page 14, line 9.

Column 6, line 57, after "device" insert --10- as appears in the originally filed specification at page 14, line 12.

Column 7, line 2, after "ventricle" insert --20 – as appears in the originally filed specification at page 14, line 22.

Column 7, line 16, after "device" insert --10- as appears in the originally filed specification at page 15, line 9.

Column 7, line 38, after "device" insert --10- as appears in the originally filed specification at page 16, line 2.

Column 8, line 18, after "ventricle" insert --20- as appears in the originally filed specification at page 17, line 19.

Column 8, line 35, change "another-alternative" to --another alternative-- as appears in the originally filed specification at page 18, line 9.

Column 8, line 51, change "1may" to --120 may – as appears in the originally filed specification at page 18, line 22.

Column 9, line 20, after "ventricle" insert --20- as appears in the originally filed specification at page 20, line 5.

Column 9, line 26, after "ventricle" insert --20 – as appears in the originally filed specification at page 20, line 10.

Column 9, line 44, change "1" to --11 – as appears in the originally filed specification at page 21, line 1.

Column 10, line 9, change "2extends" to --210 extends— as appears in the originally filed specification at page 22, line 4.

Column 10, line 14, after "ventricle" insert --20- as appears in the originally filed specification at page 22, line 8.

Column 10, line 46, after "ventricle" insert --20- as appears in the originally filed specification at page 23, line 10.

In accordance with the established procedure for handling such certificates, two copies of Form PTO-1050 (Rev. 2-93) are enclosed herewith listing the error.

Applicants do not believe that any other fees are due in connection with this submission. However, if such petition is due or any other fees are necessary, the Commissioner may consider this to be a request for such and charge any necessary fees to deposit account 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P

Kevin G. Rooney

Reg. No. 36,330

2700 Carew Tower 441 Vine Street Cincinnati, OH 45202 (513) 241-2324

K:\SPEN\08\coc trans.wpd

Printer's -Trim Line

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,808,483

Page 1 of 2

DATED

: October 26, 2004

INVENTOR(S) : Mark Ortiz et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 5

Line 45, change "34" to --3A--.

### Column 6

Line 34, after "device" insert --10-.

Line 39, after "device" insert --10-.

Line 42, after "ventricle" insert --20-.

Line 46, after "aorta" insert --30-.

Line 53, after "device" insert --10-.

Line 57, after "device" insert --10-.

### Column 7

Line 2, after "ventricle" insert --20-.

Line 16, after "device" insert --10-.

Line 38, after "device" insert --10-.

### MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917

PATENT NO. <u>6,808,483</u> No. of add'l copies @ 50¢ per page: \_\_

SUBSTITUTE FORM PTO76-22

Printer's Line

# UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,808,483

Page 2 of 2

DATED

: October 26, 2004

INVENTOR(S) : Mark Ortiz et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### Column 8

Line 18, after "ventricle" insert --20-.

Line 35, change "another-alternative" to --another alternative--.

Line 51, change "1may" to --120 may-.

## Column 9

Line 20, after "ventricle" insert --20-.

Line 26, after "ventricle" insert --20-.

Line 44, change "1" to --11-.

### Column 10

Line 9, change "2extends" to --210 extends-.

Line 14, after "ventricle" insert --20-.

Line 46, after "ventricle" insert --20-.

#### MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917

PATENT NO. \_\_6,808,483 No. of add'l copies @ 50¢ per page: \_\_